

# SURVEY RECOVERY FORM

City of Everett  
Department of Public Works

State of Washington  
County: Snohomish

Station Name: 703 54 02

Horizontal Datum: NAD83/91

Vertical Datum: NAVD88

Established By: DOT-Linn & Asso

Control Point ID: Book: 703

Page: 54

Pt#: 02

Date: 9/9/99

Section: 08

Township: 28 N

Range: 5 E

LATTITUDE: (5 decimal places) 47 55 36.99912  
LONGITUDE: (5 decimal places) 122 11 59.56126

ORTHOMETRIC HEIGHT: \_\_\_\_\_ Feet  
\_\_\_\_\_ Meters

## Washington State Plane Coordinates – North Zone

	Northing (4 decimal places)	Easting (4 decimal places)	Point Scale Factor (to 9 decimal places)	Convergence Deg Min Sec
Feet	341095.161	1305403.938	0.999947784	-01 01 02.7
Meters	103966.013	397887.916		

### HORIZONTAL DATA:

Horizontal position established by:

\_\_\_\_\_ resection survey, comments

☒ GPS survey, GPS adjustment software used: Trimble RTK, Trimbal Software

\_\_\_\_\_ other, explain: \_\_\_\_\_

surveyor's estimated relative positional accuracy: 0.4 ft n @ 0.4 ft E 95% confidence Level Constrained to DOT points GP31005-81, through GP31005-88

surveyor's estimated absolute positional accuracy: ft @ 1 sigma \_\_\_\_\_ % confidence Level

### VERTICAL DATA:

Vertical position established by: WJA

\_\_\_\_\_ differential leveling to: \_\_\_\_\_ order accuracy

\_\_\_\_\_ GPS survey, accuracy within \_\_\_\_\_ ft \_\_\_\_\_ meters

surveyor's estimated relative positional accuracy: \_\_\_\_\_ ft @ \_\_\_\_\_ 95% confidence Level

surveyor's estimated absolute positional accuracy: \_\_\_\_\_ ft @ \_\_\_\_\_ 95% confidence

## MONUMENT DESCRIPTION

A 4-inch concrete monument with a 2-inch lead plug and brass tack set in the top, down 7-inches under an iron monument case and cover.

## TO REACH

Located just east the center of Timber Hill Drive and about 510 feet southwest of the intersection of Timber Hill Drive and Ridgewood Drive. (This is a P I monument)

## REFERENCES

Az from North	Distance	Reference Description
---------------	----------	-----------------------

Month & Year Recovered:

Condition of Mark:

Recovered By: